

The VELCO logo is displayed in a bold, white, sans-serif font against a background of a scenic Vermont landscape with rolling hills and power lines.

VERMONT'S TRANSMISSION RELIABILITY RESOURCE

# System Assessment Project

## Status Update

---

November 17, 2011

# System Assessment Project

## Status Update

- **Phase One: Relay Setting Comparison**

- Contract engineer comparisons have been completed on four stations, with VELCO acceptance review completed on one station.
- No additional significant findings have been reported since Stowe.

- **Phase Two: Record Drawing Review**

- Contract engineer reviews have been completed on twelve stations, with VELCO acceptance review completed on six stations.
- No significant findings have been reported.

- **Phase Three: Relay Setting Basis**

- Contract engineer review continues for the Vernon/VY area and will be underway in December for the Essex area.
- No findings to report.

- **Phase Four: Field Verification**

- Functional testing has been completed on one station.
- Draft schedule has been developed for the end-end line testing.
- No findings to report.

# System Assessment Project

**WORK DOWN PROJECTION CURVE - Nov. 8, 2011**

